ONFIDENTIAL

Approved For Release 2001/03/17: CIA-RDP82-00457R004100380003-6
CLASSIFICATION GLICALY CONTROL - U.S. OFFICIALS ONLY

CENTRAL INTELLIGENCE AGENCY

REPORT NO.

INFORMATION REPORT

25X1A

CD NO.

25X1A

COUNTRY Hungary

DATE DISTR.

9 Jan. 19<del>49</del>

SUBJECT Road Conditions in Hungary

NO. OF PAGES

3

PLACE ACQUIRED DATE OF IN

TO CIA LIBRARY

NO. OF ENCLS.

SUPPLEMENT TO REPORT NO.

25X1X

The Soviets demanded from the Hungarian Honved Ministry a report on the conditions of the roads marked on the attached map.

The Hungarian answer contained the following data:

1. SOPRON - GYOER Road Section

From SOPRON to NAGYCENK a concrete road; from there to KAPUVAR a rolled road in fair conditions; concrete road from KAPUVAR to GYOER.

2. SOPRON - SARVAR Road Section:

From SOPRON to NAGYCENK a concrete road; from NAGYCENK on a rolled road in very poor condition.

3. SZCMBATHELY - GYCER Road Section:

As far as VAT the road is in poor condition for motor vehicles; from VAT to CSORNA a road of fair qualityon; from CSORNA on a good rolled road.

4. SZOMBATHELY - KOESZEG Road Section:

A good road throughout.

5. SZGEBATHELY - SARVAR - CELLEDOEMOEIK Road Section:

As far as SARVAR a road in a poor condition for motor vehicles; from SARVAR on a road of fair quality.

6. SZOMBATHELY - BUDAPEST Road Section:

As far as KAM several sections are under repair; from KAM onward in good condition.

CLASSIFICATION - SHORET / CONTROL - U.S. OFFICIALS ONLY															
	STATE.	·	×	NAVY		×	NSRB		DIS	TRI	BUTION				
	ARMY	Ħ	X	AIR	ŦF	X.	FBI								

### CONLINFINITY

## Approved For Release 2001/03/17: CIA-RDP82-00457R004100380003-6 SECRET/CONTROL - U.S. OFFICIALS ONLY 25X1A

### CENTRAL INTELLIGENCE AGENCY

7.	SZOMBATHELY - KOERHEND -		ZE RTG	CTTHAND	Road	Section:
	As far as KOERLERD road onward a good road.	of	fair	quality	; fr	om RCLRILLID

- 8. HAGYKANIZSA LETENYE Road Section:
  Road unserviceable for motor vehicles.
- 9. NAGYKANIZSA KESZTHELY Road Section:

  As far as GALAMBOK road of fair quality; from GALAMBOK onward road slightly better.
- NAGYKANIZSA KAPOSVAR Road Section:

  As far as BOEHOLNYE road of low quality; from BOEHOENYE on of fair quality.
- 11. <u>IERGYELTOTI KAPOSVAR Road Section</u>:

  Macadam road in a good condition; repair work is being done on some sections.
- 12. HATVAN GYOENGUOES KAPOLNA FUEZESABONY Road Section:
  First class road sith hard surface.
- 13. GYOENGYOES GALYATETOE Road Section:

  Macadam road in a good condition; also serviceable after snowfalls. The bridge before MATRAHAZA is a temporary 5-ton bridge.
- 14. GYOFNGYOES ATKAR JASZAROKSZALLAS Road Section:

  Road in a poor condition; repair work has just started.
- 15. GYOENGYOLS KARACSOND NAGYFULGED BOCOMAD HEVES road Section:

  Road in a poor condition; repair work recently started.
- 16. EGER KERECSEND doad Sections
  Lacadam road of medium quality.
- 17. BUDAPEST ASZOD HATVAN Road Sections
  First class road bridge near HATVAN is completed.
- 18. ASZOD SAIGOTARJAN Road Section:
  Road under repair; culverts 90 percent completed.
- Unserviceable for motor vehicles. Underpass of branch railway line near CSOMAD is damaged.
- 20. FOT MCGYORCD Road Section:
  Repair work under way in various sections.

# Approved For Release 2001/03/17 DIALREP 82-00457R004100380003-6

#### \*CHERRY/CONTROL - U.S. OFFICIALS ONLY 25X1A

### CENTRAL INTELLIGENCE AGENCY

NYIELGYHAZA - DEDIECLI Road Getion: Road in a fair condition1

NYIRLGYBAZA - TOKAJ Road Section:

As far as RARAMAZ road in fair condition; from RARAMAZ on of poor quality.

MAKO - SZEGED Road Section: 24.

> As far as UJSZEGED road is in a good condition; from UJSZE-GED to the bridge over the Tisza liver first class road. Approach to the SELGLD ferry is poor.

25. MAKO - HODE ECEVASARHELY Road Section:

> Road good as far as the branch; from there on a road of medium quality.

26. MAKO - TUTKONLOS Road Section:

Good road.

27. SZEGED - ROLSZKE (state border) Road Section: Road good.

28. CZEGLD - HCDIEZOEVASARHELY Road Section:

> First class road as for as the bridge near ALGYCR; from there on repair bork is under way.

SZEGLD - BAJA Road Section:

Road of medium quality.

30. SZEGED - SOLVENYHAZA Road Section:

Road conditions medium.

31. SZEGED - BUDAFEST Road Section:

First class road.

MARO - MAGYLAK Road Section:

Good road. Repair work under way before the bridge in 25×TAALVA.

33.

The report apparently only supplements provious data submitted to the Soviets as the individual road sections dealt with in the report do not show any interconnection. The only exception is the orea of SIEGOD where the coviets request for a report on road conditions may be in connections. tion with the appearance of boviet troops at that time.

1 Ampex: Report on Road Conditions Jubilitied by the "Honved" Linistry (Hungarian Linistry of Defense) on b. vict lequest.

SECULT CONTROL/US COMICIALS CHAY